

Release Notes



TRIMBLE FIELD SYSTEMS
OCTOBER 2025

TRIMBLE X9 Firmware Version 1.3.3.0077

Introduction

Trimble® announces the release of X9 firmware version 1.3.3.0077 to support the new X9 Core LT configuration. X9 Core LT provides a new entry level option with 40-meter range. This important firmware update is for all X9 scanners and includes Wi-Fi updates for Canada.

Overview

- Support for new Core LT configuration. See product bulletin for new configuration and upgrade part numbers.
- Wi-Fi update to enable 5GHz channels in Canada

Note: Firmware version 1.3.3.0077 upgrades all X9 scanners (8990 and 8991 serial numbers). Downgrades to earlier versions will be prohibited on configurable X9 scanners with 8991 serial numbers.

Software Requirements

Trimble Perspective version 2025.20 and higher is required to ensure compatibility with firmware version 1.3.3.0077. A new version of Trimble FieldLink will be available soon to support the new X9 Core LT configuration.

For more information

For more information, contact your local Trimble Distribution Partner.

© 2025, Trimble Inc. All rights reserved. Trimble and the Globe & Triangle logo are trademarks of Trimble Inc., registered in the United States and in other countries. All other trademarks are the property of their respective owners.